

	A	B	C	D	E	F	G
1	## North America Emission Control Area Fuel Oil Non-Availability Report						
2	## ECA0100						
3	## 1	2	3	4	5	6	7
4	##						
5	##(Include Double Pound for comments, not form fields)						
6	##Report Form ID	Ship Operator Name	Vessel Name	Flag Country	IMO ID Number	Date of ECA First Notice	Location of ECA First Notice
7							
8							
9	ECA01000	Teekay Shipping Ltd	Ashkini Spirit	Bahamas	9239484	20/01/2017	Marcus Hook
10							
11							
12							
13							

	H	I	J	K	L
1					
2					
3	8	9	10	11	12
4					
5					
6	Name of Ports after First Notice	Name of Last Port before ECA Entry	Name of Port with Fuel Oil Supply Disruption	Name of Original Fuel Supplier with Disruption	Number of Fuel Suppliers Contacted
7					
8					
9	Jose Monobuoy & South Sabine	Jose Monobuoy	NA	NA	NA
10					
11					
12					
13					

	M	N	O	P	Q	R
1						
2						
3	13	14	15	16	17	18
4						
5						
6	Date of Entry in the ECA	Time of Entry in the ECA	Sulfur Content of Non-Compliant Fuel Oil	Projected Hours on Main Propulsion	Name of First POC	Compliance Fuel Oil Available at First POC?
7						
8						
9	11/2/2017	1650	2.07	2 South Sabine	Yes	
10						
11						
12						
13						

	S	T	U	V	W
1					
2					
3	19	20	21	22	23
4					
5					
6	Plan to Bunker Compliant Fuel Oil at First POC?	Number of fuel suppliers contacted at First POC	Name of Second POC	Compliant Fuel Oil at Second POC?	Plan to Bunker Compliance Fuel Oil at Second POC?
7					
8					
9	Yes	NA	Lake Charles	Yes	Yes
10					
11					
12					
13					

	X	Y	Z	AA	AB
1					
2					
3	24	25	26	27	28
4					
5					
6	Number of Fuel Suppliers Contacted at the Second POC?	Date of Exit from ECA?	Time of Exit from ECA?	Has this vessel operated in the ECA in previous 12 months?	Number of Separate Visits to the ECA
7					
8		26/02/2017	600	Yes	2
9	NA				
10					
11					
12					
13					

	AC	AD	AE	AF	AG
1					
2					
3	29	30	31	32	33
4					
5					
6	Number of Ports visited in the ECA	Previously submitted ECA0100 forms?	Number of Submitted Reports	Designated Corporate Official Name	Designated Corporate Official E-mail
7					
8	5	0	1	Mr Paul Roberts	paul.roberts@teekay.com
9					
10					
11					
12					
13					

	AH	AI
1		
2		
3	34	35
4		
5		
6	Designated Corporate Official Phone Number	Description of Actions to Achieve Compliance
7		
8	0044 7767003868	All going well vessel will not run out of bunkers
9		We have stemmed 200 mt LSMGO to go onboard pm/18th
10		Vessel has been delayed since arrival at South Sabine and berthing has constantly been pushed back
11		We had original stemmed 400 mt LSMGO to go onboard Lake Charles after discharge, once we knew
12		delays would occur I informed agents I wished to take them before berthing, on Monday 13th, it took until
13		Thursday 16th for agents to tell me that pilots stated this was not possible.